

Machine Cutting Accessories



TH-98 Twin Tip Adapter

Adjustable twin adapter for 2 cuts simultaneously using one torch. Adjust from 30 mm to 305 mm wide (special widths available on request) "O" ring sealed. Large capacity (up to 200 mm to each tip).



BV-98-2 Beveling Head

Use with natural gas or propane only. Increase speed and quality of bevel cuts. 6290 cutting tips can be used. Uses specially designed 1390-3H replacement heating tip for optimum results.



96-DC Oxygen Saver

Dual control oxygen saver for 3 hose torches. Fits to oxygen line. Moving the lever adjusts the flame from an extreme flame for piercing and quick starts to a soft small flame for economy and quality. Advantages are reduced oxygen and gas consumption, very high cut quality, square edges, slag-free cuts with fast starts. Not recommended for acetylene.



C-98-V2 Flash Check Valve for Cutting Oxygen Inlet On Three Hose Torches

Stops reverse flow of gases. Recommended when cutting oxygen valve is remote from torches. Cutting capacity up to 250 mm.



S-98-C Adjustable Tip Adapter

Allows adjustment of tip to any angle without moving the torch "O" ring sealed. Large capacity, (up to 200 mm) calibrated 90°.



886-CVTL/CVTR Check Valves

Reverse flow check valves for preheat only. Help prevent dangerous reverse flow mixing of gas in hose and regulators (see page 75 for complete check valve information).